




GENERAL NOTE: CAREFULLY REMOVE ALL WRAPPING MATERIALS AND ENSURE ALL PARTS ARE ACCOUNTED FOR. ASSEMBLE ON A CLEAN FLAT SURFACE TO AVOID SCRATCHES. DO NOT DISCARD THE PACKAGING UNTIL ITEM IS FULLY ASSEMBLED.



CT-609 CT-609-1 CT-611 CT-611-1 CT-611-2

- ① X1
- ② X1
- ③ X1
- ④ X4 M8 X 20
- ⑤ X6 M8 X 35
- ⑥ X1
- ⑦ X1 5MM
- ⑧ X1 6MM

