

ASSEMBLY INSTRUCTION ITEM NO.: 7275-CCH

THANK YOU FOR PURCHASING THIS QUALITY PRODUCT.

BE SURE TO CHECK ALL PACKING MATERIAL CAREFULLY FOR SMALL PARTS THAT MAY HAVE COME LOOSE INSIDE. THE CARTON DURING TRANSIT.

STEP 1	PART LIST						
Q		NO	DESC	SIZE (MM)	SKETCH	QTY	
	H FRONT A B B	A	BACK	750X550 X130		1 PC	
		в	SEAT	550X520 X120		1 PC	
		с	ARMREST	445X300 X50	$\bigcirc \bigcirc \bigcirc$	1 SET	
STEP 3	STEP 4	D	STARBASE	R350X100		1 PC	
A		E	CASTORS	90X60X55		5 PCS	
C B	c	F	GASLIFT COVER	R32.5XL65		1 PC	
		G	GASLIFT	R25XL220		1 PC	
dc	C d	н	SWIVEL TRAY	510X270 X205		1 PC	
HARDWARE LIST							
d b) d	NO	DESC	SIZE (MM)	SKETCH	QTY	
STEP 5	FINISH	а	SCREW	M6X20	0	4 PCS	
		b	SCREW	M6X30		4 PCS	
		с	SCREW	M8X45		4 PCS	
		d	SPANNER	M6		1 PC	
		е	SCREW COVER	R9X8	())	4 PCS	
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	MADE IN CHINA						