




M60EC103				①		②		③		
EN	Assembling scheme			15/18 M42B0001	x8	5/11x34 M42B0022	x8	∅8x30 M42H0001	x8	
DE	Montageschema									
FR	Schéma d'assemblage									




④		⑤		⑥	
∅4/18 M45A3013	x8	∅10/13 M45A2029	x4	4.5x45 M42A0110	x2
⑦		⑧		⑨	
4,0x15 M42A0056	*	6,3x13 M42C0029	*	20x17 M42J0027	*




EN	*Configuration depends on order option
DE	*Die Konfiguration hängt davon der Bestelloption ab
FR	*La configuration dépend de l'option de commande

1




2




3



2





1




3






4






5



6



7




M60EC004







1 / 1

Assembling scheme

Required tools:




Hardware:




Hinge positions


1H/2H/3H




4H





5H



6H



4



With lock