




Assembling scheme

Required tools:




Hardware:




Product:


a)



b)




c)




d)




Parts:




a)




b)



c)





d)




a) & b) x4
c) & d) x3

1



A



2

