

# M60EP011

Surinkimo schema


Схема сборки

Assembling scheme

Reikalingi įrankiai:

Инструменты для сборки:

Requiring tools:



4mm

①



x2

②



x4

③



x11

④



x2

⑤



x2

⑥




x2

⑦




x2


1





2




1



2



BPA182  
BPA222



BPA183  
BPA223