

Surinkimo schema


Assembling scheme

Схема сборки


Reikalingi įrankiai

Requiring tools


Инструменты для сборки



①




②



M6

③



M6

SUC010; SUC110

x5

x4

-

SUC114; SUC314; SUC011; SUC214; SUC414; SUC111

x5


x4

x6

SUC010; SUC110



SUC114; SUC314;
SUC011; SUC214;
SUC414; SUC111



M60ER010