## ASSEMBLY INSTRUCTIONS



## (Box 1)

BOX OF HEADBOARD & FOOTBOARD


BOIL OF THE HODOTH D & LOOT BOTH D		
No	ITEM	Qty
A	Headboard	1 pc
В	Footboard	1 pc
С	Headboard Leg (L/R) Nail leg	1 pc
D	Bed Slats	4 pcs
Е	Bed Slats Support	4 pcs


## (Box 2) BOX OF SIDE RAIL


No	ITEM	Qty
F	Side Rail	2 pcs

## (Box 1)

HARDWARE LIST			
No	ITEM	Qty	
1	JCBC M6 x 30mm	6 pcs	
2	SPRING WASHER 1/4" Rbw	6 pcs	
3	Flat Washer 1/4"ID x 13mmOD Blk	6 pcs	
4	ALLEN KEY m4x65mm Blk	1 pc	
5	ALLEN KEY m5x65mm Blk	1 pc	
6	Flat Head Chipboard Screw m4x32mm Rbw	8 pcs	
7	Flat Head Chipboard Screw m4x20mm Rbw	4 pcs	
8	Metal leg	2 pcs	







NOTE: MUST TIGHTEN SCREWS PERIODCALLY WITH USE SCREW WILL BECOME LOOSE CHECK TIGHTNESS OF ALL SCREW EVERY 6-8 WEEKS.